

**DATE:** May 5, 2010

**TITLE:** The Pelican 2010 SabreLite™ LED Recoil™ Has Received A Safety Approval Upgrade

**PRODUCTS AFFECTED:** 2010 SabreLite LED Recoil, 2010PL SabreLite Recoil LED

**DETAILS:**

The Pelican 2010 SabreLite LED Recoil now has Edison Testing Labs - ETL Class I II III, Division 1 Approvals (for gas, dust & fiber/flyings).



**2010 SabreLite Recoil LED**

Official approvals are:




Class I II III Division 1 Groups ABCDFG T4 (Energizer), T3 (Duracell & Panasonic)



**2010PL SabreLite Recoil LED**

Two approvals were removed:

- FM Class I, Div. 1 Gp. D T4/Class I, Div. 2 Gp. ABCD T4/CL II, III, Div. 1, Gp. FG
- CSA Class I, Div. 1 Gp. D T3C/CL. I, Div. 2 Gp. ABCD T3C / CL II, Div. 1, Gp. FG



HAZARDOUS AREA ELECTRICAL GUIDELINES					
	SUBSTANCE	TYPICAL ENVIRONMENTS	US CLASSIFICATION	EUROPEAN CLASSIFICATION	VOLATILITY
CLASS 1	Flammable Gasses, Vapors or Liquids (Acetylene, Hydrogen, Ethylene, Propane)	- Oil Refinery - - Paint Warehouse - - Offshore Oil Rig - - Spray Booth -	Division 1 (Hazard Likely)	Zone 0 (Hazard Certain)	MOST ↑ ↓ LEAST
			Division 2 (Hazard Not Likely)	Zone 1 (Hazard Likely)	
CLASS 2	Combustible Dusts (Metals (div. 1 only), Coal, Grain)	- Coal Mine - - Grain Silo - - Munitions Factory - - Hay Storage Facility -	Division 1 (Hazard Likely)	Zone 0 (Hazard Certain)	
			Division 2 (Hazard Not Likely)	Zone 1 (Hazard Likely)	
CLASS 3	Ignitable Fibers & Flyings (Machined Magnesium)	- Paper Mill - - Woodworking Facility - - Textile Mill - - Cotton Gin -	Division 1 (Hazard Likely)	Zone 2 (Hazard Not Likely)	
			Division 2 (Hazard Not Likely)	Zone 0 (Hazard Certain)	
				Zone 1 (Hazard Likely)	
				Zone 2 (Hazard Not Likely)	

**Click The Graphic To Learn More on Safety Approvals**

